



Issue Date: January 13, 2015

Revision Date/#: _____

Expiration Date: _____

PACKAGE COMMERCIAL

DS-PC011502

PRODUCT ALERT

Units Involved: RKKL-B072 and RLKL-B072 Wiring Harness

Date Codes Involved: Units manufactured date codes F3911 thru F3814

Details:

The RKKL-B072 and RLKL-B072 were originally released with a 12-pin economizer wiring harness on the unit. A change notice was released on September 27, 2011 (date code F3911) to switch back to a 9-pin economizer wiring harness to permit accessories designed for the predecessors to the RKKL-B072 and RLKL-B072 to be used. When the harness was changed the 2-pin PL6 connector for the discontinued JCI economizer was not provided with the harness. The (-)XRD-01RCCAM3 & (-)XRD-01RCCBM3 economizer cannot be used with units manufactured date codes F3911 thru F3814 without the replacement of the 9-pin economizer wiring harness.

Recommended or Required Action:

If you install or replace an existing economizer with the (-)XRD-01RCCAM3 & (-)XRD-01RCCBM3 economizer in a unit manufactured in the date code listed above, the wiring harness must be replaced. RKKL-B072 models require a 12-pin 45-42522-108 to use with the (-)XRD-01RCCAM3 or (-)XRD-01RCCBM3 economizer. RLKL-B072 models require a 12-pin 45-42522-109 harness to use with the (-)XRD-01RCCAM3 or (-)XRD-01RCCBM3 economizer.

Ruud Heating and Cooling
Rely on Ruud.™

