

Issue Date: April 10, 2015



PARTS/PROSTOCK

DS-PS041503

PRODUCT ALERT

Units Involved: Various 90% models originally built with Honeywell gas valves: 60-22866-01; 60-100394-01; 60-100394-02; 60-100394-03 and 60-104158-01.

Date Codes Involved: All

Details:

Beginning in November 2014, through March 26, 2015, some orders of gas valves: 60-22866-01; 60-100394-01; 60-100394-02; 60-100394-03 and 60-104158-01 were substituted with part number 60-105055-01.

This substitution has since been determined to be unsuitable for 90% furnace applications. 60-105055-01 is a relatively "fast opening" valve, and as a result may cause "hard ignition" in 90% furnace applications.

Note, this substitution is acceptable for both 80% single stage furnace and single stage package unit applications.

We have published new parts lists on RuudParts.com based on the [Gas Valve Model Substitution chart](#) to specify the correct replacement based on unit type.

Recommended or Required Action:

If any 60-105055-01 valves have already been installed in 90% furnace applications, we recommend these be changed to either 60-100394-03 or 60-103901-01. We will provide a \$75.00 labor allowance for replacement of the gas valve. Please reference WCN/Authorization code (DC-PS041503) when filing a claim through the iWarranty system.

Also, please update any internal cross-referencing systems to cancel this substitution. The replacement gas valve should be selected based on the parts lists, or by using the [Gas Valve Model Substitution chart](#).

Ruud Heating and Cooling
Rely on Ruud.™

